

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: STATEMENT
(Fuel Spill)

DATE OCCURRED _____

DATE REPORTED 11/9/85

TIME OCCURRED _____

TIME REPORTED 1213 1215

LOCATION(S) OF OCCURRENCE:

REPORTED BY:

PHONE NO(S):


R/O

SUMMARY:

Craig Baker, Dept. of Ecology, came by the station at 1205 and advised that Crosby and Overton were about to resume pumping of the southwest pumphouse oil separators. He also advised that KING-TV was filming the clean-up procedures, both at FlightCraft, and at the pumphouse. After consulting with Chief Olson, a call was left with the Public Works Dispatcher, 255-2531, to have Public Works Public Relations Officer Sue Robinson advised of the situation, should she desire to comment.

An attempt to Contact Airport Manager Don Smith was made at 1245 hrs; No answer. Assistant Manager Jack Frazelle was updated at 1245 about what progress was being made in the clean-up efforts. He was advised that attempts had been made to contact Manager Smith at his residence. He advised that he would continue attempts to reach Smith during the afternoon.

OFFICERS:



ACTION: